WEST Search History

Hide Items Restore Clear Close

DATE: Thursday, April 15, 2010

Hide?	<u>Set</u> Name	Query	<u>Hit</u> Count
Prior A	\ <i>r</i> 1		
DB=	PGPB,	USPT; PLUR=YES; OP=OR	
	L45	L44 and @pd > 20091221	2
1	L44	L42 or L32	161
	L43	L42 not L32	63
1	L42	L41 and ((ni or nickel) near3 (layer or foil or film or coat\$))	69
3	L41	L34 or L35	237
	L40	L39 not L32	0
	L39	(L35 or L38) and L26	14
3	L38	L34 not L32	173
3000	L37	L36 and L32	0
	L36	L35 not L32	83
	L35	(("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al" or ti3al) and ((braz\$ or join\$) same (ni or nickel)) and ((phase) and (ni or nickel)))	97
	L34	(("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al" or ti3al) and (braz\$ or join\$) and ((phase) same (ni or nickel)))	192
}***	L33	(("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al" or ti3al) and (braz\$ or join\$) and (phase) and (ni or nickel))	438
1	L32	L30 or L28	98
	L31	L29 not L28	85
1	L30	L29 not L13	98
} ::	L29	(("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al" or ti3al) and (braz\$ or (join\$ and phase) or ((ni or nickel) and phase))) and L26	98
3	L28	L27 and L26	13
	L27	(("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al" or ti3al) and (braz\$ or (join\$ and phase) or ((ni or nickel) and phase))).clm.	97
	L26	(428/615 or 428/660 or 428/680 or 428/668 or 228/262.9 or 228/262.3 or 228/262.1 or 228/262.31 or 228/262.71 or 228/262.72 or 228/262.8 or 148/516 or 148/524 or 148/527 or 148/528 or 148/535 or 148/537 or 148/669)![CCLS]	5029
DB=	EPAB,	JPAB,DWPI; PLUR=YES; OP=OR	
	L25	L24 or L19	135
3	L24	L15 not L19	61
}:	L23	L22 not L19	0
<u></u>)	L22	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al" or ti3al) and join\$ and phase	26
-	L21	L20 not L19	0
	L20	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al" or ti3al) and braz\$	51
	L19	L17 or L14	74

	L18	L17 not L14	22
**	L17	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al") and join\$ and phase	26
<u></u>	L16	L15 not L14	64
	L15	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al") and (ni or nickel) and phase	67
	L14	L12 or L13	52
	L13	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al") and ("ti.sub.3al")	1
	L12	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al") and braz\$	51
DB=	USPT;	PLUR=YES; OP=OR	
	L11	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub.3al") and braz\$	183
	L10	"ti.sub.3al"	29
	L9	"ti.sub3.al"	0
DB=	EPAB,	JPAB,DWPI; PLUR=YES; OP=OR	
	L8	"ni.sub.3al"	1
	L7	"ni.sub3.al"	0
	L6	"ti.sub.3al"	1
	L5	"ti.sub3.al"	0
	L4	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub3.al") and (ni or nickel)	367
	L3	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub3.al") and (ni or nickel) and ("ti.sub3.al")	0
	L2	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub3.al") and (ni or nickel) and ("ti.sub3.al" and tialni)	0
,	L1	("met sheet" or tial or "ti-al" or "titanium aluminide" or "ti.sub3.al") and braz\$	51

END OF SEARCH HISTORY